

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	pH	Alk	Phos	Sili	Y/N		
1	7.7		1		V	< <have< td=""><td>County: Lincoln Agency: REGION 2</td></have<>	County: Lincoln Agency: REGION 2
2	7.9	<u> </u>			1	been met for	ENTRY POINT
3	1			<del></del>	1	this day?	EP-A
4							PWS ID 4100925
5	7.8				a y		1.00
6	7.9			-	1-1-	, som	SW LINCOLN CO WATER DIST
7	5.9			5 5 4 T	1		··· · \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
8	7.7	-			1	Sample	period: April 2021
9	7.9		i		y.		Month/Year
10						Number of	avourcione during this month.
11	*	1.					excursions during this month:
12						(Over 9 exc	cursions in 6 months is a violation.
13	7.9	· \			1/	Cumulative)	and Distribution excursions are  . An 'excursion' is any day in which the
14	7.9				1	water qualit	ty parameter(s) fall below the minimum
15	7.9				4	set by the S	State.
16	7.9				7		MAY 1 0 2021
17						5.5	Data Mgmt & Complianc
18	-		4.	- 3		Refe	Drinking Water Program
19	7.8				7		Minimum Motor Osselite
20	7.8	-	A A -	1. 13	Y		Minimum Water Quality Parameter(s) as set by State:
21	7.9				1		i didilieter(s) as set by State:
22	7.9				y		pH 7.1
23	7.9			. 1	y	v .	The second secon
24					-		
25							
26	7.9			1	7	* * * * * * * * * * * * * * * * * * *	
27	7.9				Y		
28	7.9				4		Name: BARRY ARNOLD
29	7.8				4		ture: Barry Arnoll
30	7.8/		:		7	Date _	Phone#: 541-547-4951
31					1	Send t	o DWP within 10 days after end of
	= Excı	ursion)	Total	Nic		sampli	ng period
n = N = Excursion) Total N's							

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml